eCopy ScanStation™ Supported TWAIN Devices

The following Canon TWAIN devices are supported by the eCopy ShareScan® v4.35 for ScanStation:

imageRUNNER C1022
imageRUNNER 1023iF/1025iF
imageRUNNER 2200/2800/3300
imageRUNNER 2220/3320
imageRUNNER 2230
imageRUNNER 2270*/2870*/3570*/4570*
Color imageRUNNER C3080/C3480
Color imageRUNNER C2380/C3580
(not available in the US)
Color imageRUNNER C2550
imageRUNNER C3170
Color imageRUNNER C2620/ C3220
imageRUNNER 2830
Color imageRUNNER C2880/3380
imageRUNNER 3025/3030/3035/3045
imageRUNNER C3100
Color imageRUNNER C3200
imageRUNNER 3230/3225/3235/3245
imageRUNNER 3530
Color imageRUNNER C4080/ C4580/ C5180/C5185
imageRUNNER 5000/6000
imageRUNNER 5020/6020
imageRUNNER 5050/5055/5065/5075
imageRUNNER C5058/C5068
imageRUNNER 5070/ 5570**/6570**
Color imageRUNNER C5800/C6800
Color imageRUNNER C5870/C6870
Color imageRUNNER C5880/C6880
imageRUNNER 7086/7095/7105
imageRUNNER 7200/8500/105
imageRUNNER 8070/9070/105+
imagePRESS C1
CLC4040/CLC5151 (not available in US)
imagePRESS1110/1125/1135
imageRUNNER ADVANCE C5030/C5035/C5051/C5045
imageRUNNER ADVANCE C7055/C7065
imageRUNNER ADVANCE C9065 PRO / C9075 PRO

Please reference the Scanner Supported Device List for information on compatible Canon DR scanners.

* These devices are not supported by the eCopy ScanStation when being used with a Canon B2 or B2 v2 Security Kit.

** These devices are not supported the eCopy ScanStation when being used with a Canon B3 Security Kit.

Unless otherwise noted eCopy ShareScan works with Canon controllers, security kits and data encryption kits.

Notes:
Please note the following configurations are not supported by eCopy ScanStation:

- VRS TWAIN is not supported by ScanStation
- EFI Fiery TWAIN is not supported by ScanStation

December 2009