

The following Ricoh Embedded (ESA - SDK/J) families of devices are supported by eCopy ShareScan v4.35:

Ricoh v7 Devices - SDK/J Version 7.x or higher - Java VM Card Pre-Installed				
Ricoh	Lanier	Savin	Gestetner	Notes
MP C6501 MP C7501	MP C6501 MP C7501	C9065 C9075	LD365C LD375C	

Ricoh v5.0x Devices-SDK/J Version 4.13 or higher-Java VM Card Type J				
Ricoh	Lanier	Savin	Gestetner	Notes
MP 6001 SP	LD360sp	9060sp	MP 6001 SP	
MP 7001 SP	LD370sp	9070sp	MP 7001 SP	
MP 8001 SP	LD380sp	9080sp	MP 8001 SP	
MP 9001 SP	LD390sp	9090sp	MP 9001 SP	
Pro 907EX	Pro 907EX	Pro 907EX	Pro 907EX	
Pro 1107EX	Pro 1107EX	Pro 1107EX	Pro 1107EX	
Pro 1357EX	Pro 1357EX	Pro 1357EX	Pro 1357EX	

Ricoh v5.0x Devices-SDK/J Version 4.13 or higher-Java VM Card Type J (i)				
Ricoh	Lanier	Savin	Gestetner	Notes
MP C2050 MP C2550	LD520C LD525C	C9020 C9025	MP C2050 MP C2550	Devices require 1G total memory for scanning – new Ricoh Seg. 1 devices <i>These models replace the C2500 / C3000 v2.x devices.</i> <i>These models replace the C3500 / C4500 v2.x devices</i>
MP C2800 MP C3300	LD528C LD533C	C2828 C3333	MP C2800 MP C3300	
MP C4000 MP C5000	LD540C LD550C	C4040 C5050	MP C4000 MP C5000	

Ricoh v4 Devices - SDK/J Version 4.18 or higher - Java VM Card Pre-Installed				
Ricoh	Lanier	Savin	Gestetner	Notes
MP 2851 MP 3351	MP 2851 MP3351	9228SP 9233SP	LD528SP LD533SP	

MP 4001 MP 5001	MP 4001 MP 5001	9240SP 9250SP	LD140SP LD150SP	
--------------------	--------------------	------------------	--------------------	--

<b>Ricoh v4.1 Devices - SDK/J Version 4.13 or higher - Java VM Card Type I (i)</b>				
Ricoh	Lanier	Savin	Gestetner	Notes
MP C2050 MP C2550	LD520C LD525C	C9020 C9025	MP C2050 MP C2550	<i>Devices require 1G total memory for scanning – new Ricoh Seg. 1 devices</i> <i>These models replace the C2500 / C3000 v2.x devices.</i> <i>These models replace the C3500 / C4500 v2.x devices</i>
MP C2800 MP C3300	LD528C LD533C	C2828 C3333	MP C2800 MP C3300	
MP C4000 MP C5000	LD540C LD550C	C4040 C5050	MP C4000 MP C5000	

See the Important Notes below for additional information.

<b>Ricoh v4 Devices - SDK/J Version 4.07 or higher - Java VM Card Type F</b>				
Ricoh	Lanier	Savin	Gestetner	Notes
MP 2550 MP 3350	LD425 LD433	9025 9033	N/A N/A	<i>These models replace The 3500 / 4500 v1.x devices.</i>
MP 4000 MP 5000	LD040 LD050	9040 9050	N/A N/A	
MP C6000 MP C7500	LD260c LD275c	C6055 C7570	MP C6000 MP C7500	
ProC900 ProC900s				

See the Important Notes below for additional information.

<b>Ricoh v2 Devices</b>					<b>Supports mixed originals</b>
<b>Requires SDK/J Version 2.09 or higher - Java VM Card Type C</b>					
Ricoh	Lanier	Savin	Gestetner	Notes	See Note #
MP C2000	LD420C	C2020	N/A		
Pro 906EX Pro 1106EX Pro 1356EX	Pro 906EX Pro 1106EX Pro 1356EX	Pro 906EX Pro 1106EX Pro 1356EX	Pro 906EX Pro 1106EX Pro 1356EX	<i>These Pro models replace Ricoh discontinued 9000 / 1100 / 1350.</i>	
MP 6000 MP 7000 MP 8000	LD260 LD270 LD280	8060 8070 8080	MP 6000 MP 7000 MP 8000	6000 / 7000 8000 models replace Ricoh discontinued 5500 / 6500 / 7500.	
MP C2500 MP C3000	LD425c LD430c	C2525 C3030	DSc525 DSc530	<i>Discontinued by Ricoh. Replaced by 2800 / 3300 (Type i) models. All devices remain supported.</i>	✓
MP C3500 MP C4500	LD435c LD445c	C3535 C4040	DSc535 DSc545	<i>Discontinued by Ricoh. Replaced by C4000 / C5000 (Type i) models. All devices remain supported.</i>	✓
MP 9000 MP 1100 MP 1350	LD190 LD1110 LD1135	8090 8110 8135	Dsm790 Dsm7110 Dsm7135	<i>Discontinued by Ricoh. Replaced by Pro 906 / 1106 / 1356 EX models. All devices remain supported.</i>	✓

MP 5500 MP 6500 MP 7500	LD255 LD265 LD275	8055 8065 8075	DSm755 DSm765 DSm775	Discontinued by Ricoh. Replaced by MP 6000 / 7000 / 8000 models. All devices remain supported.	<b>N/A</b>
-------------------------------	-------------------------	----------------------	----------------------------	---	------------

See the Important Notes below for additional information.

<b>SDK/J Version 1.3 or higher Java VM Card Type B</b>			
<b>Ricoh</b>	<b>Lanier</b>	<b>Savin</b>	<b>Gestetner</b>
2051	LD151	4051	DSm651
2060	LD160	4060	DSm660
2075	LD175	4075	DSm675
MP 2510	LD325	8025e	DSm725e
MP 3010	LD330	8030e	DSm730e
MP 3500	LD335	8035e	DSm735e
MP 4500	LD345	8045e	DSm745e
3025	LD225	8025	DSm725
3030	LD230	8030	DSm730
3035	LD235	8035	DSm735
3045	LD245	8045	DSm745
3224C	LD124c	C2410	DSC424
3228C	LD328c	C2824	DSc428
3235C	LD335c	C3528	DSc435
3245C	LD345c	C4535	DSc445
3260C	LD160c	C6045	DSc460
Color 5560	LC155	SDC555	CS555

See the Important Notes below for additional information.

**Important Notes:**

1. If a device is not listed above, it is not supported.
2. Shaded rows indicate devices in the same device family.
3. Devices must have scanning capabilities – typically indicated as “S” in the model #.
4. Models indicated as “replaced” continue to be supported.
5. Java VM Card Types A & D (printers), E (wide format; non-US) and G, and H, are not supported. As new platforms and devices are released by Ricoh, eCopy will evaluate adding support for them.
6. Image preview of v2 and v4.x devices shows only the last page; v1 devices (B&W) show a page at a time. All devices allow the ability to scroll through the previews.
7. Ricoh Embedded devices do not have Zoom available during preview.
8. JAR compatibility matrix:

<b>Device Type &amp; minimum SDK/J version</b>	<b>Language</b>	<b>eCopy .jar version (ShareScan version)</b>	<b>Installation Method</b>	
			<b>SD Card</b>	<b>Web Install</b>
v1 1.03	English ONLY	1.0.0.34 (4.1 & 4.2)	Supported	N/A
v2 2.09 or higher	EFIGS	2.1.0.13 (4.1 & 4.2) 4.0.0.8 (4.2) 4.3.0.41 (4.3)	Supported	Supported

v4 4.07 or higher	EFIGS	4.0.0.8 (4.2) 4.3.0.41 (4.3)	Supported	Supported
v4.1 4.13 or higher	EFIGS	4.0.0.8 (4.2) 4.3.0.41 (4.3)	Supported	Supported
v5.0X	EFIGS	4.3.0.41 (4.3)	N/A	Supported